



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Phone (306) 653-6600 Fax: (306) 242-5599

- Site Service Report -

IRD SO#: 10785N

From: Steven Schroeder

Project Name: Maine LTPP

Project Location: I-95 mm 200.2

Service Date(s): 2-9-08

Weather: sunny

IRD Ref:

To: Bruce Myers

Job Description:

Perform semi annual site inspection

Work Completed:

Performed an electrical check and visual inspection of site. All sensors and electronics look good.

Work Remaining:

Parts Used:

Mileage / Travel Time:

600 miles/ 10 hours

Time Spent on Site:

2 hours

Notes:

Action Items:

Item	Action Required	Ownership
1.		



IRD

Site Service Sheet

[Clear](#)System Type: iSinc/KistlerDate: 2/9/2008State: MaineLocation: Northbound

Job #: _____

Site #: _____

Directions: I-95 mm 200.2

Loops	Lane	Lead	Trail	Lead	Trail	Lead	Trail	Lead	Trail
		1							
	Resistance	0.7 ohms	0.7 ohms						
	Leakage	inf	inf						
	Inductance uH	120.0	120.0						
	Frequency	high	low						

Serial #

Kistler	Lane - 1								
		1	2	3	4	5	6	7	8
	Amplitude	ok	ok	ok	ok				
	Capacitance	10.8 nF	10.6 nF	11.4 nF	10.6 nF				
	Resistance	inf	inf	inf	inf				

Serial #

Kistler	Lane - 2	1	2	3	4	5	6	7	8
	Amplitude								
	Capacitance								
	Resistance								

Serial #

Kistler	Lane - 3	1	2	3	4	5	6	7	8
	Amplitude								
	Capacitance								
	Resistance								

Serial #

Kistler	Lane - 4	2	3	4	5	6	7	8
	Amplitude							
	Capacitance							
	Resistance							

Serial #

System

A/C Service	
Power Supply	
Solar Panel	17.7
Back-Up	14.6
System Input	
Modem Power	14.6
Phone off	
Phone on	

Site Full Operating Capacity **Pass**Technician: Steven Schroeder Date: 2/9/2008

